

Annexure D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: 28/08/2025

It is certified that the existing building DECENT CONVENT SCHOOL (name of the building or premises) at A.V Enclave Bhamian Kalan Ludhiana

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>4</u>	<u>—</u>	<u>—</u>	<u>—</u>	<u>—</u>	<u>—</u>

The building is owned/occupied by Decent convent school (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD (Name of Department/ Govt.) on 28/8/2025 (date of inspection) in the presence of Mr. Sunil Mehta (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 28/8/2025 for a period of One year years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 28/8/2025 at by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : [Signature]
 Name : Indarpal Singh
 Designation : S.D.O
 Name & Address of Department/ Office: _____

Sub Divisional Engineer
Provincial Sub Division No.2,
PWD, B&R Br., Ludhiana